

DANCING SNOWCOUPLE AND SNOWMEN ORNAMENTS AND CANDY SERVERS

Mold Numbers

1614 Snowmen with Gifts Orn.
1615 Snowmen with Brooms Orn.
1616 Snowmen with Candy Canes Orn.
1617 Eskimo Snowmen Orn.
1618 Snowmen with Snowflakes Orn.
1619 Hit the Beach Snowmen Orn.
1620 Lover Snowman Cuddle Orn.
1621 Snowflake Snowman Cuddle Orn.
1622 Couch Potato Snowman Cuddle Orn.
1623 Cocoa/Coffee Snowman Cuddle Orn.
1640 Dancing Snow Couple
1642 Snowmen Candy Servers

MATERIALS NEEDED

OPAQUE STAINS: Vanilla, White, Electric Blue, Victorian Green, Peach Blush, Christmas Red, Marigold Yellow, Bright Orange, Sky Blue and Black.

SPECIALTIES: Crystal Ice Glimmerz and Opal Glitter It

MISC: High-fire ornament wire.

PREPARATION: Place high-fire ornament wire in ornament while cast is still damp. Replace texture to seam lines using the TL-9 texture tool. Fire to cone 05.

NOTE: The following instructions are exactly the way the pieces were finished on the flyer. If you would like to speed up the process and avoid the antiquing, basecoat the pieces using Sky Blue and drybrush the white areas as directed under drybrush. Before continuing with the drybrush instructions, rebasecoat black and colored areas of the snowmen using the following colors to the appropriate areas using the flyer as your guide: Black, Electric Blue, Christmas Red, Marigold Yellow and Bright Orange.

BASECOAT: Water down basecoat colors to the consistency of light cream. Paint color to areas as follows: White areas – Vanilla, blue areas – Electric Blue, red areas- Christmas Red, yellow areas – Marigold Yellow, orange areas – Bright Orange, green areas – Victorian Green and black areas – Black.

ANTIQUAGE: Using Glistening Blue, antique all pieces, wipe off excess with a soft cloth.

DRYBRUSH: 2 to 3 coats of Vanilla to all white areas, follow with 2 coats of White. Blush Snowpeople's cheeks lightly with Peach Blush. On all red areas

drybrush with 1 to 2 coats of Christmas Red followed with a coat of Christmas Red and Bright Orange mixed; lightly highlight with a small dab of Vanilla added to your brush. Drybrush Black to all black areas followed with 2 to 3 coats of a small amount of White added to your brush. All other colors, drybrush the original basecoat color back over followed with Vanilla added to your brush to highlight. The more coats with Vanilla added to your brush the lighter the highlight will become.

SHADE: If desired, shade pieces for more definition using Night Blue.

PAINT: All eyes and eyelashes using Electric Blue for the irises. Paint Crystal Ice Glimmerz to all fur and snowflakes. Paint Opal Glitter It to all ornaments.